FICATION
de reporting
14 CFR 91.411
ound to meet

[redacted]

Date	Recording Tach/ Hour Meter Time	Total Time In Service	Description of work performed
2018 5/11	185.76	185.76	Fuel tank removed because of leak. Cockpit seat top area cut and removed to show fuel tank. Installed factory new tank I/A/W instructions; Fuel Tank Replacement by Bud Yerly, Custom Flight Creations Inc. and Europa Builder's Manual Chapter 16. Install new hose connections to tank using Chemseal B2. Enlarged access holes on button from 4 inches to 5. Reenforce the area around holes with four layers of bid fiberglass. All fuel tanks supports were removed and remade I/A/W Custom Flight Creations Fuel Tank Support MOD. Completed Conditional Inspection this date. Right main tire replaced, wheel bearings cleaned and greased. K&N filter cleaned and oiled . I certify this aircraft has been inspected on May 11, 2018, in accordance with the scope and detail of appendix D of Part 43 and had been found to be in condition for safe operation Richard L. Stockton [redacted]

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2017 6/26	160.6		160.6	revised Weight and Balance. Removed earth alternator, voltage regulator, capacitor, Installed Camit alternator kit CAEARF13.5. New W&B Emptied Weight 976, CG 59.81583, Moment 58380.25 [redacted] Richard L. Stockton [redacted]
2017 12/20		173.45		Removed Vacuum Pump [redacted] Richard L. Stockton [redacted]

YEAR:	RECORDING TACH TIME
DATE	
2018 5/11/18	185.76

or Repair

or,
r kit

YEAR: / DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	**Description of Inspections, Tests, Repairs and Alterations** Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2018 5/11/18	185.76		185.76	Cylinder head bolts torque checked I/A/W Jabiru JEM0002-7, and Table 10. Install new spark plug, set gap and torqued I/A/W JEM0002 7, 9.10 and Table 10. Drained Oil; Oil Cooler and replaced Oil Filter. Oil sample taken and Oil filter cut open; found no metal. 100 hours inspection completed I/A/W JEM0002-7, Table 14. [redacted] Richard L. Stockton [redacted]