YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	**Description of Inspections, Tests, Repairs and Alterations** Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				5/29/2019 N201HH Tach: 4760.96 TT: 4760.96
				Tested ELT per FAR 91.207. Replaced battery. Next replacement due June 2021.
				Removed Challenger air filter, previously installed per STC SA01669CH. Installed owner provided Brackett housing and new air filter element, part number BA6210. No change in weight and balance.
				Replaced steering horn assembly, part number 720095-001, with rebuilt unit, serial number 112618-002. Replaced pivot bushing with oversized bushing, part number L025-914007-004-010
				I certify that this aircraft has been inspected in accordance with an annual inspection and was found to be in airworthy condition. [redacted] A&P [redacted] 1A

chnician or

60.96

1.

led owner

, serial
mber

spection and

6424 1A

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				Flite Instruments and Avionics 2310 S. Airport Blvd Ste 11 Chandler AZ 85286 CS # 6FIR926C 480-516-0308
				Reg.# / A/C Make / Model / S/N / Tach-bobb N 201HA Mooney M20J 24-6053 4760
				I certify that the transponder tests, including data correspondence, required by § 91.413, have been performed and found to comply with 14 CFR part 43, appendix F. .
				Date 05/08/19 [redacted]
				Work performed by [redacted] Work Order # 7526
				Inspected by [redacted]

YEAR 20 19 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	**Description of Inspections, Tests, Repairs and Alterations** Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	5/29/2019		N201HH	Tach: 4760.96 TT: 4760.96
				Replaced tail cone pivot hardware, 2 AN174-20A bolts, AN5H-32 bolt, AN960-416 and AN960-516 washers and AN365-428 and AN310-5 nuts.
				[redacted]

YEAR 20 20 DATE
2/12/20

nician or

nd

YEAR 20 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	**Description of Inspections, Tests, Repairs and Alterations** Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2/12/20	4781.8		4781.8	
	Resealed rt brake cylinder, Installed New			
	brake linings both sides, service brakes			
	return A/c. To Service			
	[redacted]			

YEAR 2020 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
5/12	4787.92		4787.92	See Prop Log - OVERHAULE Prop Installed
5/13	?		?	A/C Totaled in off Airport landing. [redacted]

YEAR 20____ DATE	RECORDING TACH TIME