



Photo 1 – N803TH at the accident site (courtesy of the Alaska Mountain Rescue Group)



Photo 2 - Right side of fuselage during detailed examination



Photo 3 - Left side of fuselage at detailed examination



Photo 4 - Right wing sections during detailed examination



Photo 5 - Left wing sections at detailed examination



Photo 6 - Cockpit and instrument panel



Photo 7 - McCauley model 3GF34C703 propeller indicating blade deformations




Photo 8 - Pratt & Whitney PT6-114A turbine engine indicating fractured shaft




Photo 9 - No. 3 and 4 bearing scavenge pump indicating metallic debris



Photo 10 - Engine oil tank with small blue plastic cap evident



Photo 11 - Engine Compressor turbine (CT) disk bore area with circumferential rubbing marks