



Photo 1 – N9084J PA-32R-301 at the accident scene near Bethel. (Compliments of Alaska State Troopers)



Photo 2 - Engine Oil deposit on the airport ramp. (Compliments of Alaska State Troopers)



Photo 3 - Top left view of Lycoming IO-540-K1G5 exhibiting a hole and fractures at the no. 4 cylinder and a missing oil dipstick.




Photo 4 - No. 3 and 5 pistons and connecting rods exhibiting thermal damage and fractures.



Photo 5 - Crank shaft journals exhibiting thermal discoloration and damage.




Photo 6 - Right oil cooler (Aero-Classic P/N 8000074) with fracture at the brazed plates.