



Photo 1 – Both Fracture Surfaces of Lug Fitting



Photo 2 – Fracture Surface of Lug Fitting on Hydrasorb Side



Photo 3 – Fracture Surface of Lug Fitting on Extension Tube Side