



Photo 1 – N5020D propeller and fuselage damage.



Photo 2 - N5020D fuselage damage.



Photo 3 - N5020D buckled engine firewall.