



**Photo 1 – View of the flight track information (courtesy of the NTSB).**



**Photo 2 – View of the termination of the flight track information (courtesy of the NTSB).**



**Photo 3 – View of the accident site with a low cloud layer present, shortly after the accident occurred, looking to the northwest (courtesy of the Maui County Police Department).**



**Photo 4 – View of the accident site on a clear day, looking to the northwest (courtesy of the NTSB).**



**Photo 5 – View of the fuselage and the empennage (courtesy of the NTSB).**



**Photo 6 – View of the fuselage and engine (courtesy of the NTSB).**




**Photo 7 – Aerial view of the accident site on the mountain and of runway 5 at Molokai Airport (MKK) (courtesy of the Maui County Police Department).**



**Photo 8 – Exemplar: FAA aviation weather camera in Alaska (courtesy of the FAA).**





**Photo 10 – Exemplar: Gustavus Airport (GST), Gustavus, Alaska, FAA aviation weather camera (southeast) clear day reference image (courtesy of the FAA).**

Thu 21 Mar 2019 17:48:52 UTC  
Thu 21 Mar 2019 09:48:52 AKDT

Gustavus - SouthEast  
See <https://avcams.faa.gov> for more information



FAA advisory weather product

**Photo 11 – Exemplar: Gustavus Airport (GST), Gustavus, Alaska, FAA aviation weather camera (southeast) instrument meteorological conditions image (courtesy of the FAA).**




Photo 12 – Designated mountainous terrain in Hawaii (courtesy of the Electronic Code of Federal Regulations).