



Photo 1 – Video clip of N9878R taxiing back after aborted takeoff. (Courtesy of Phil Stanger)



Photo 2 - Video clip of the airplane after takeoff. (Courtesy of Marty Spinde)



Photo 3 - Video clip of the airplane climbing to the south. (Courtesy of Marty Spinde)



Photo 4 - Video clip from south facing security camera seconds before impact. (Courtesy of Marianne Shoppmeyer)



Photo 5 - Westerly view of wreckage.



Photo 6 - Easterly view of wreckage.



Photo 7 - Left wing.



Photo 8 - Hydraulic reservoir and flap pump and flap selector indicating down positions.



Photo 9 - Wreckage at hangar during examination.



Photo 10 - Left flap and aileron indicating impact deformation.



Photo 11 - Engine and propeller.