



Photo 1 –N3607Y Cessna 210. (Source: Federal Aviation Administration)



Photo 2 - Right wing and aileron substantial damage. (Source: Federal Aviation Administration)



Photo 3 - Landing gear actuator exhibiting fractures. (Source: Federal Aviation Administration)



Photo 4 - Landing gear actuator exhibiting circumferential fracture.