



**Photo 1 – View of the intact left main landing gear and the separated right main landing gear (courtesy of the pilot).**



**Photo 2 – View of the intact left main landing gear and the separated right main landing gear (courtesy of the pilot).**



**Photo 3 – View of the substantial damage to the right wing and the right aileron (courtesy of the pilot).**



**Photo 4 – View of the substantial damage to the right wing and to the right aileron (courtesy of the pilot).**