



Photo 1 –N185KB Cessna 185 inverted at the accident site. (Source: owner)



Photo 2 - Airplane after recovery before examination. (Source: FAA)



Photo 3 - Continental IO-520 before the engine examination. (Source: FAA)



Photo 4. - Front view after wings removed. (Source: FAA)




Photo 5 - Engine control linkages. (Source: FAA)



Photo 6 - Sparkplugs and fuel injectors with fuel from fuel lines captured in bags. (Source: FAA)