



Repair Station No. [REDACTED]
2425 Merrill Field Dr
Anchorage, AK 99501
Phone: [REDACTED]
Fax: [REDACTED]
Date: 11/12/2018, 2:07 PM

CUSTOMER INFORMATION

SILVER SKY, LLC
[REDACTED]
PO BOX 91332
ANCHORAGE, AK 99509
[REDACTED]
[REDACTED].com

Customer Invoice Repair Order: 25130

Total Balance Due **\$50.00** (See Below For Cost Detail)

Item: 1 - Airworthy Airframe

Discrepancy	Hours	Subtotal
CARBURETOR TEST, LET SS KNOW WHAT WE FIND BEFORE REPAIR	Flat	50.00
MA-3SPA		
P/N 10-4895		
S/N BF02276		

Corrective Action

DIRT AND A LOT OF WATER CAME OUT OF THE DRAIN PLUG OF THE CARB BOWL WHEN WE PULLED IT. IN OUR EXPERIENCE ENGINES WILL NOT RUN ON WATER AND IT IS A REAL POSSIBILITY THAT EXCESSIVE WATER IN THE FUEL MAY HAVE CAUSED ENGINE FAILURE. NO OTHER WORK PERFORMED.

Labor: \$50.00	Parts: \$0.00	Shipping: \$0.00	Outside Repair: \$0.00	Item Subtotal:	\$50.00
----------------	---------------	------------------	------------------------	----------------	---------

Additional Charges

Pilot Services	Tire Disposal	EPA Charge	Oil Analysis	Shop Supplies	Fuel	Misc.	Subtotal
0.00	0.00	0.00	0.00	0.00	0.00	0.00	\$0.00

Labor Summary

Shop Labor: \$50.00 Outside Repair: \$0.00

0.00 hours were needed to complete this Repair Order

N2809L

Total Labor:	\$50.00
Total Parts:	\$0.00
Total Shipping:	\$0.00
Total Outside Repair:	\$0.00
Additional Charges:	\$0.00
Tax:	\$0.00
Amount Due:	\$50.00
Deposit:	\$0.00
Balance Due:	\$50.00

Important Information

Labor estimates are not final and do not include any parts necessary to complete the order. Alaskan Aircraft Engines, Inc is not responsible for loss due to fire, theft, or any other cause beyond our control.

Work Authorized by:

SILVER SKY, LLC or Authorized Representative

Date