




Photo 1 – Accident airplane's right main landing gear bellcrank assembly. Sheared bellcrank pivot bolt outlined in red circle.



Photo 2 – Accident airplane's sheared bellcrank pivot bolt with smeared fracture features and deformation consistent with ductile overstress fracture from shear loading.