



**Photo 1 –Aerial photograph of N5163E Cessna 185 inverted fuselage in deep snow at the accident site.
(Source: Department of Interior (DOI))**



Photo 2 - Distant aerial photograph of the wreckage at the scene of the accident. (Source: DOI)



**Photo 3 - Aerial photograph of the main wreckage and separated left wing about two months after the accident.
(Source: DOI)**




Photo 4. - Wreckage at the accident site after the snow melted and before recovery showing the propeller and left landing gear, the left wing, and fuselage. (Source: DOI)



Photo 5 - Inverted fuselage wreckage. (Source: DOI)



Photo 6 - Left side of engine area. (Source: DOI)



Photo 7 - Upright fuselage during recovery efforts. (Source: DOI)