



Photo 1 – Accident airplane at accident site. Photo provided by unknown.



Photo 2 – Tailwheel steering arm's scored and damaged inside radius.



Photo 3 – Tailwheel steering arm’s scored and damaged inside radius.



Photo 4 - Compression spring in its respective attach point. Note, no spacer present.



Photo 5 - Compression spring's sharp and damaged spring end.