



Photo 1 – Photo of left main landing gear “gearbox” assembly and landing gear leg. (Photo provided by FAA)



Photo 2 – Side view photo of left main landing gear “gearbox” and landing gear leg. (Photo provided by FAA)



Photo 3 – Photo of skid marks on runway, looking east. (Photo provided by FAA)



Photo 4 – Photo of accident airplane, left side, after recovery. (Photo provided by FAA)



Photo 5 – Photo of right wing, which depicts runway abrasion damage to outboard portion of wing tip fairing. (Photo provided by FAA)