



Photo 1 – Rear view of damaged empennage and right wing (Photo courtesy of the FAA)



Photo 2 – Rear view of damaged empennage and left wing (Photo courtesy of the FAA)