



Photo 1 – View of damaged empennage (Photo courtesy of the pilot)



Photo 2 – View of damaged lift strut (Photo courtesy of the pilot)