



**Photo 1 – Accident airplane (Source: K Bay Air, LLC)**



**Photo 2 – Fractured right main landing gear leg (Source: K Bay Air, LLC)**