



Photo 1 –Left side view of accident airplane at accident site. Photo provided by owner.



Photo 2 – . Right side view of accident airplane at accident site. Photo provided by owner.



Photo 3 – Cockpit view of the nail still installed in the yoke gust lock of accident airplane at accident site. Photo provided by the owner.