



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Alaska Region

Photo Array

ANC22LA080



Photo 1 – View of the airplane and left float in Whiskey Lake (Photo courtesy of Alaska State Troopers)



Photo 2 – View of the airplane on the shore of Whiskey Lake after recovery.



Photo 3 – View of partially separated section on hull of the right float.



Photo 4 – View of the empennage (Photo courtesy of Textron)



Photo 5 – View of patch and screws on the hull of the right float. (Photo courtesy of Textron)



Photo 6 – View of the left float.



Photo 7 - View of multiple patches on the left float.