

ANC23FA042

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of where the airplane came to rest from the departure end of the airstrip.



Photograph 2 - View of the tree with impact damage and fragments of red paint.



Photograph 3 - View of the impact damage and red paint fragments.



Photograph 4 - View from the airstrip from the beginning towards the departure end. The red arrow indicates the location of the tree that was struck.



Photograph 5 - View of the main wreckage where it came to rest.



Photograph 6 - Rear view of the wreckage and the left horizontal stabilizer.



Photograph 7 - View of the horizontal stabilizers and rudder.



Photograph 8 - View of the leading edge damage to the left horizontal stabilizer (Courtesy of Textron Aviation)



Photograph 10 - View of tree sap and embedded tree fibers in the leading edge of the horizontal stabilizer.