

ANC23LA049

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aerial view of accident site (Courtesy of FAA)



Photograph 2 - View of left wing root (Courtesy of FAA)



Photograph 3 - View of right wing root (Courtesy of FAA)



Photograph 4 - View of right wing leading edge (Courtesy of FAA)



Photograph 5 - View of right wing aft jury strut (Courtesy of FAA)