

ANC23LA051

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of left side of engine compartment. (Courtesy of FAA)



Photograph 2 - View inside the No. 1 cylinder after removal from engine, note the remaining portion of the exhaust valve stem.



Photograph 3 - Caption of photograph (Courtesy of FAA)