

ANC23LA062

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Damaged right wing (Courtesy of NTSB Investigator)**



**Photograph 2 - Damaged left horizontal stabilizer (Courtesy of NTSB Investigator)**