

ANC23LA063

INVESTIGATION PHOTOGRAPH



Photograph 1 - Damaged rudder and vertical stabilizer (Courtesy of Operator)