

ANC23LA068

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aft view of damage to the airplane's tail. (Courtesy of owner)