

ANC23LA078

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane after recovery (Courtesy of NTSB)



Photograph 2 - Accident airplane after recovery (Courtesy of NTSB)



Photograph 3 - Fuel control inlet filter (Courtesy of NTSB)