

ANC23LA080

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the airplane inverted, where it came to rest. (Courtesy of the Federal Aviation Administration)



Photograph 2 - View of airplane after recovery. (Courtesy of Federal Aviation Administration)



Photograph 3 - View of damage to the right wing (Courtesy of Federal Aviation Administration)