

ANC23LA081

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane and engine where it came to rest. (Courtesy of FAA)