

ANC23LA084

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of the right wing struts (Courtesy of Pilot)



Photograph 2 - Image of the right wing trailing edge (Courtesy of Pilot)



Photograph 3 - Image of the empennage (Courtesy of Pilot)