


ANC24LA011

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of the vertical stabilizer and rudder (Courtesy of FAA)



Photograph 2 -Image of damage to the fuselage (Courtesy of FAA)