

ANC24LA016

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident helicopter at accident site (Courtesy of FAA)




Photograph 2 - View of the horizontal stabilizer (Courtesy of FAA)



Photograph 3 - View of the horizontal stabilizer (Courtesy of FAA)



Photograph 4 - View of the left side of the tail rotor (Courtesy of FAA)



Photograph 5 - View of the damage to the tail rotor drive shaft (Courtesy of FAA)