

ANC24LA017

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of fuselage and the separated empennage containing the vertical fin, horizontal stabilizer, and tail rotor (Courtesy of Operator)



Photograph 2 - Image of Kaflex driveshaft after removal from wreckage (NTSB Photo)



Photograph 3 - Image of clutch output bearing outer race with three roller elements adhered (NTSB Photo)