

ANC24LA019

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of aircraft post recovery (Courtesy of owner)



Photograph 2 - Left hand view of accident aircraft after recovery (Courtesy of owner)



Photograph 4 - Left side of Tail of aircraft after recovery (Courtesy of Owner)