

ANC24LA028

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of accident airplane viewed from the front (Courtesy of Operator)



Photograph 2 - Image of fractured engine mount tubing (Courtesy of Operator)



Photograph 3 - Image of outboard left wing viewed from above (Courtesy of Operator)



Photograph 4 - Image of outboard right wing viewed from above (Courtesy of Operator)