

ANC24LA036

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of accident airplane (Courtesy of Airport Operations)



Photograph 2 - Image of damaged right wingtip and aileron (Courtesy of Airport Operations)



Photograph 3 - Image of right main landing gear axle (NTSB Photo)