

ANC24LA049

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident airplane after recovery.



Photograph 2 - View of engine during engine examination