

ANC24LA055

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to the bottom of the wing and aileron (Courtesy of operator)



Photograph 2 - View of damage to the top of the wing (Courtesy of operator)



Photograph 3 - View of wingtip damage (Courtesy of operator)