

ANC24LA057


INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the front of the airplane where it came to rest. (Courtesy of FAA)



Photograph 2 - View of right side of the airplane where it came to rest. (Courtesy of FAA)



Photograph 3 - View of the cracked No. 9 cylinder (Courtesy of FAA)