


ANC24LA077


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Push pull tube fractured at bell crank (Courtesy of FAA)



Photograph 2 - Bolt missing from flex plate yoke assembly (Courtesy of FAA)



Photograph 3 - Bolt and washer from flex plate assembly in tail boom (Courtesy of FAA)



Photograph 4 - Push pull tube with witness signature from bolt (Courtesy of FAA)