

ANC24LA093

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to the bottom of right wing (Courtesy of pilot)



Photograph 2 - View of the top of the right wing missing vortex generators (Courtesy of FAA)



Photograph 3 - View of damage to right spar (Courtesy of pilot)