

ANC24LA101

INVESTIGATION PHOTOGRAPHS



Photograph 1 - repair of spar and wing ribs (Courtesy of Owner)