

ANC25LA009

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane at accident site (Courtesy of owner)



Photograph 2 - Right gear leg folded under fuselage (Courtesy of owner)