

ANC25LA012

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane at accident site (Courtesy of owner)



Photograph 2 - Damage to the right wing lift strut (Courtesy of owner)