

Carburetor Icing Probability Graph – ANC25LA019

Airplane: Piper PA-18-150

Engine: Lycoming O-360-A2A

Fuel: 100LL

Accident Date: 02/20/2025

Accident Location: Wasilla, AK

Accident Time: 1642 AKST

Weather: Observation Facility (AWS) reported
temperature 39° F; dew point 19° F

Source: Federal Aviation Administration
Special Airworthiness Information Bulletin CE-09-35
Carburetor Icing Prevention

