

ANC25LA029

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane inverted (Courtesy of Owner)



Photograph 2 - Damage to right wing (Courtesy of Owner)