

ANC25LA030

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Airplane with collapsed gear leg (Courtesy of Owner)**



**Photograph 2 - Damage to landing gear box assembly (Courtesy of owner)**



**Photograph 3 - Bolt as found after accident in landing gear (Courtesy of Owner)**



**Photograph 4 - Fiber locking nut from landing gear assembly (Courtesy of NTSB)**



**Photograph 5 - Bolt from landing gear assembly (Courtesy of NTSB)**