

ANC25LA036

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the airplane and damage to left wingtip (Courtesy of airfield manager)



Photograph 2 - Damage to windscreen and left side of fuselage (Courtesy of airfield manager)



Photograph 3 - View of a stick lodged in the airframe around the windscreen (Courtesy of airfield manager)



Photograph 4 - View of damage to left strut. (Courtesy of airfield manager)