

ANC25LA041

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to right strut. (Courtesy of FAA)



Photograph 2 - View of damage to left leading edge. (Courtesy of FAA)